

TECHNICAL SERVICE BULLETIN

Part #:	DDR-06222015	Engine:	Duramax
Date:	03/10/2025	Title:	Duramax Camshaft Position Sensor Exciter Ring

All Duramax long blocks require the camshaft position sensor exciter ring to be transferred from the original camshaft gear or replaced. Ensure the part number you are using matches your VIN application.

